

Area	Issue	Priority
Canal Street	Pavement outside the furniture shop	1
Canal street	Crossing facilities difficult to reach and the cross road	1
Kinnoull Street/Scott Street	Cables hanging off the wall	1
Mill street/bridge lane	Position of crossing push buttons	1
Mill street/ bridge lane	George street lack of dropped kerbs at disabled bays	1
Pedestrian zone	Bollard	1
Pedestrian zone	A boards	1
Pedestrian zone	Tactile at entry/ exit or pedestrian zone	1
Pedestrian zone	Who is allowed on pedestrian zone	1
Pedestrian zone	Parking on pedestrian zone	1
Pedestrian zone	Areas where buses need cut back	1
Pedestrian zone	Loose utility covers	1
Route from train/bus station	Leonard bridge junction dangerous to cross	1
Route from train/bus station	Loose tactile at king street crossing	1
Route from train/bus station	Overgrown hedges along route	1
South street	Repair tactile at crossing at pig halie	1
South street	Loose tactile at pedestrian crossing	1
South street	Potholes in pavements	1
Various locations	Advertising boards	1
Various locations	Ongoing maintenance	1
Various locations	Road works signs on pavement/ dropped kerbs	1
Various locations	Placement of push buttons	1
Canal street	Various dropped kerb along street	2
King street	No tactile at dropped kerbs	2
Kinnoull street/ Scott street	Entrance to Scott street car park has difficult sight lines	2
Kinnoull street/ Scott street	Outside Sandeman pavement is uneven	2
Mill Street/Bridge lane/george street	George street water gathers at dropped kerb	2

Area	Issue	Priority
Mill street/ Bridge lane/george street	Bus stops have lack of colour contrast	2
Pedestrian zone	Bins and temporary obstructions	2
Pedestrian zone	Tactile around the circle statue	2
Pedestrian zone	Vehicles on pedestrian zone	2
Pedestrian zone	Lack of vehicle signage	2
Pedestrian zone	No dropped kerbs at Sainsbury's end of high street	2
Pedestrian zone	Pavement at the HGV delivery at St Johns Centre	2
Pedestrian zone	Lack of colour contrast	2
Pedestrian zone	Placement on benches	2
Route from train/ bus station	A route needs to be identified	2
Route from train/ bus station	Speed of cars in the area	2
Route from train/ bus station	Lighting on Kings Place under the bridge	2
Train station	Missing dropped kerbs from road entrance	2
Train station	Access around the station	2
Train station	Pavement around the car park is obstructed by hotel stairs	2
Train station	Clutter outside the train station on the pavement	2
Various locations	Street crossings	2
Various locations	Sight lines of dropped kerbs	2
Various locations	Tactile not always back to buildings	2
Various locations	Potholes on pavements	2
Bus station	Dropped kerbs are high and difficult to negotiate	3
Canal street	No tactile at dropped kerbs to cross car parks	3
Canal street	Obstructions such as bus shelter and bench	3
Canal street	Crossing at Charles street- furniture shop to car park	3
King street	Dropped kerbs are high and difficult to negotiate	3
King street	Potholes on pavements	3
Kinnoull street/ Scott street	Difficult dropped kerb outside smart parking	3

Area	Issue	Priority
Kinnoull street/ Scott street	Atholl street to Mill Street uneven pavement	3
Mill street/ bridge lane/George street	Lighting in vennels is not great	3
Mill street/ bridge lane/George street	Lack of dropped kerbs at Foundry	3
Pedestrian zone	Outdoor seating	3
Pedestrian zone	Pavement alongside Caledonia housing	3
Pedestrian zone	Lack of lighting in vennel to Caledonia housing associate	3
Pedestrian zone	Type of benches	3
Pedestrian zone	Pavement around city hall	3
Pedestrian zone	Signage around city centre	3
Pedestrian zone	No signage to show through routes eg to concert hall	3
Route from train/ bus station	Crossing points throughout the journey	3
Route from train/ bus station	Various dropped kerbs along route	3
Route from train/ bus station	Crossing across Leonard St/ Cale Road	3
South Street	Railings causing obstruction at King Street crossing	3
South Street	Crossing lines at king street crossing	3
South street	Gradient of pavement makes it difficult to negotiate	3
Train station	Lack of signage	3
Various locations	Tactile at car park entrances	3
Various locations	Signage on one post	3
Pedestrian zone	Narrow pavements	4

