

Those highlighted yellow are programmed for the start of this year and white are for future programming.

SOUTH AREA		LOCATION-FROM/TO	DESCRIPTION	LENGTH	AREA	RATE	COST	CUM TOTAL	Designer	Contractor	Comments
<b>Capital</b>											
<b>RECONSTRUCT FAILED CARRIAGEWAY</b>											
<b>2017-18</b>											
9	u/c	Heughfied Road, Bridge of Earn	Partial reconstruction and resurface	534	3204	45.00	95000.00	95000.00	JMacK	Tayside Contracts	SRMCS Score low TEX/Profile/cracking
12		Kirkgate	Supply only - slabs for shared space		371	200.00	0.00	95000.00		n/a	NO SRMCS Data available
<b>2018/19 Onwards</b>											
12		Canal Crescent, Perth	reconstruction	110	880	45.00	39600.00	39600.00			NO SRMCS Data available
12	u/c	Foundry Lane	Renew/replace setts		700	35.00	24500.00	64100.00			NO SRMCS Data available
7		Abercairney Place Blackford	Reconstruction	78	156	35.00	5460.00	69560.00			SRMCS Score 20-29 for TEX and PROFILE
12		Blackfriars Wynd/Mews	Blockwork Repairs		1400	35.00	49000.00	118560.00			SRMCS Score 75 for TEX and PROFILE
<b>TRADITIONAL OVERLAY</b>											
<b>2017/18</b>											
1	C401	From Ballindean to entrance to teen Ranch	40mm Taycoat	550	2640	17.00	44880.00	44880.0	DT	Tayside Contracts	Shape carriageway to stop flooding
1	u/c	Daleally cres Errol	40mm Taycoat	330	1815	17.00	30855.00	75735.0	JMacK	Tayside Contracts	All kerbing has been raised up for overlay
1	C405	C405 Woodside to Inchtore road from junction U142 to near Lochton farm	40mm Taycoat	852	4089	17.00	69513.00	145248.0	JMacK	Tayside Contracts	Carriageway is rotten and needs reshaping on corners

1	C484	Errol Rd Invergowrie from station road to bridge No 10 near Kingoodie	Taycoat	1100	4400	17.00	74800.00	220048.0	DT	Tayside Contracts	Road has been temporary patched for years
2	B953	junction C405 to new entrance to wind mill	Taycoat	1681	8405	17.00	142885.00	362933.0	JMacK	Tayside Contracts	Road is passed being patched with quarry HGVs
1	U155	Muiredge Rd A90 to new HRA joint	Taycoat	830	4150	17.00	70550.00	433483.0	DT	Tayside Contracts	Road is now under great pressure with HGVs
6	u/c	Ewanfield Road, Crieff	Taycoat half width	260	1665	17.00	28305.00	461788.0	JMacK	Tayside Contracts	SRMCS Very little Data
9	u30	College Road, Methven	Taycoat Plane one side)	311	1800	20.00	36000.00	497788.0	JMacK	Tayside Contracts	SRMCS score low for TEX but 59 for profile
<b>2018/19 Onwards</b>											
1	u/c	Dryburgh Terr Invergowrie	Taycoat	220	770	30.00	23100.00	23100.0			Widening to carriageway, kerbing, and 40mm overlay
1	u/c	Johnston Ave Invergowrie	Taycoat	180	720	17.00	12240.00	35340.0			Road has been temporary patched for years
7	B935	Forteviot Village	Taycoat	356	2490	17.00	42330.00	77670.0			SRMCS score low for TEX
1	C401	From Teen Ranch to B953	Taycoat	584	2803	17.00	47651.00	125321.0			SRMCS score 59 with 2 sections
<b>Overlay Carriageway</b>											
<b>2017/18</b>											
2	B953	Balbeggie Inchture Rd phase 2	Proprietary	1000	5000	6.00	30000.00	30000.00			
2		Leetown Village	Proprietary			6.00	0.00	30000.00			
8	ZU238	Back Loop Crook village	Proprietary		2500	6.00	15000.00	45000.00			

8	ZU241	Drum village	Proprietary		2000	6.00	12000.00	57000.00			
1	ZC412	From B935-Dunning	Proprietary		5000	6.00	30000.00	87000.00			
8	U/C	High St Kinross access into car/m	Proprietary		1000	6.00	6000.00	93000.00			
8	U/C	Muirpark, Kinross	Proprietary	166.5	1039.2	6.00	6235.20	99235.20			
8	U/C	Muirgrove, Kinross	Proprietary	177.5	1060.8	6.00	6364.80	105600.00			
<b>2018/19 Onwards</b>											
12	u/c	Crammond Place, Perth	Proprietary		3000	6.00	18000.00				
12	u/c	Westray Court, Perth	Proprietary		900	6.00	5400.00				
12	u/c	Stronsay Court, Perth	Proprietary		1000	6.00	6000.00				
12	u/c	Rona Court, Perth	Proprietary		1300	6.00	7800.00				
12	u/c	Lingay Court, Perth	Proprietary		900	6.00	5400.00				
12	u/c	Harris Court, Perth	Proprietary		750	6.00	4500.00				
12	u/c	Gilsay Place, Perth	Proprietary		3000	6.00	18000.00				
12	u/c	Eriskay Place, Perth	Proprietary		2000	6.00	12000.00				
12	u/c	Neave Court, Perth	Proprietary		900	6.00	5400.00				
12	u/c	Brora Court, Perth	Proprietary		1700	6.00	10200.00				
12	u/c	Shuna Court, Perth	Proprietary		1400	6.00	8400.00				
12	u/c	Mull Place, Perth	Proprietary		2800	6.00	16800.00				
12	u/c	Cara Place, Perth	Proprietary		1500	6.00	9000.00				
12	u/c	Cumbræe Place, Perth	Proprietary		900	6.00	5400.00				

12	u/c	Lismore Court, Perth	Proprietary		1200	6.00	7200.00				
12	u/c	Tiree Place, Perth	Proprietary		800	6.00	4800.00				
12	u/c	Staffa Court, Perth	Proprietary		1100	6.00	6600.00				
12	u/c	Coll Place, Perth	Proprietary		1000	6.00	6000.00				
12	u/c	Iona Court, Perth	Proprietary		1500	6.00	9000.00				
12	u/c	Jura Street, Perth	Proprietary		1400	6.00	8400.00				
12	u/c	Oronsay Court, Perth	Proprietary		600	6.00	3600.00				
12	u/c	Sanda Court, Perth	Proprietary		800	6.00	4800.00				
12	u/c	Uist Place, Perth	Proprietary		2400	6.00	14400.00				
12	u/c	Imrie Place	Proprietary		650	6.00	3900.00				
12	u/c	Newton Place	Proprietary		850	6.00	5100.00				
12	u/c	Nimmo Avenue	Proprietary		3000	6.00	18000.00				
12	u/c	Nimmo Place	Proprietary		1600	6.00	9600.00				
		VIEWLANDS RD FAIRIES RD- GLASGOW RD	Proprietary	320	2368	6.00	14208.00				
6	u/c	Dollerie Tce, Crieff	Proprietary		3944	6.00	23664.00				
6	u/c	Highland Rd/Cresc Offshoots - Crieff	Proprietary			6.00	0.00				
6	u/c	Laggan Rd Crieff	Proprietary			6.00	0.00				
6	u/c	Commissioner St/Meadow Lane - Crieff	Proprietary			6.00	0.00				
10	u/c	Upper Woodland - Perth	Proprietary			6.00	0.00				
10	u/c	Cherrybank Grove - Perth	Proprietary			6.00	0.00				
10	u/c	Braeside Gardens - Perth	Proprietary			6.00	0.00				
10	u/c	Cedar Place	Proprietary		1450	6.00	8700.00				

		Perth									
10	u/c	Pickletullum Road	Proprietary		3100	6.00	18600.00				
	u/c	Craigieknowes Avenue	Proprietary		950	6.00	5700.00				
9	u/c	Brontonfield Dr Bridge of Earn	Proprietary		2750	6.00	16500.00				
7	u/c	Rossie Place Auchterarder	Proprietary	90	510	6.00	3060.00				
1	B953	from Balbeggie to Bow br farm	Proprietary	2342	12412	6.00	74472.00				Carriageway tired of patching
1	u/c	Station Rd Invergowrie full length	Proprietary	500	2850	6.00	17100.00				Carriageway potholed & high complaints
1	u/c	Church Lane Errol full length	Proprietary	112	450	6.00	2700.00				Carriageway potholed & high complaints
1	C403	Littleton den from U142 to A923	Proprietary	1900	9120	6.00	54720.00				Carriageway tired of patching
1	ZC412	Full Length	Proprietary		6000	6.00	36000.00				
7	U/C	Ancaster Way Muthill	Proprietary								
7	U/C	Pitkeloney Terrace Mithill	Proprietary								
2	U/C	Elm Grove Scone	Proprietary								
1	U/C	Burnside Rd Invergowrie	Proprietary								
2	U/C	Mayfield Rd Terr Scone	Proprietary								
2	U/C	Douglas Rd Scone	Proprietary								

2	U/C	Gannochy Rd Perth	Proprietary								
		Castleton Rd Auchterarder	Proprietary								
	u/c	Ancaster Way Muthill	Proprietary								
	u/c	Pitkelnoy Terrace Muthill	Proprietary								
	u/c	Tummel Place Comrie	Proprietary								
	u/c	Lochay Dr, Comrie	Proprietary								
	u/c	Garry Place, Comrie	Proprietary								
	u/c	Dochart Place, Comrie	Proprietary								
	U/C	Almond Place, Comrie	Proprietary								
2	U/C	Dunbarney Ave, Bridge of Earn	Proprietary								
9	U/C	The Meadows, Bridge of Earn	Proprietary								
9	U/C	Clayton Rd, Bridge of Earn	Proprietary								
9	U/c	Earn Grove, Bridge of Earn	Proprietary								
2	U/c	Gannochy Rd, Perth	Proprietary								
2	U/c	Elm Grove, Scone	Proprietary								
2	U/C	Goshen Terrace Scone	Proprietary								
2	U/C	Goshen Cres Scone	Proprietary								
2	U/C	Craigroyston Rd Scone	Proprietary								

2	U/C	Douglas Rd, Scone	Proprietary								
2	U/C	Mayfield Rd, Scone	Proprietary								
2	U/C	Birch Row, Scone	Proprietary								
1	U/C	Gowrie Rd, Errol	Proprietary								
1	U/C	Gowrie Pl, Errol	Proprietary								
	U/C	Tay Pl, Comrie	Proprietary								
2	U156	Kilspindie Rd from C402	Proprietary	400	1200						
		Greenhaugh Way Braco	Proprietary								
		Ancaster Way Muthill	Proprietary								
		Pitkelony Terrace Muthill	Proprietary								
		Beechgrove Terrace Perth	Proprietary								

**PLANE OFF EXISTING SURFACE AND RESURFACE CARRIAGEWAY**

11	u/c	Rannoch Rd - Campsie Rd to Firbank Rd	Plane off & HRA 40mm		1955	25.00	48875.00	48875.00		Tayside Contracts	SRMCS Score High 75 /Profile/cracking
7	A823	New Patch end to Orchil Rd	HRA Plane & Resurface	612	4590	22.00	100980.00	149855.00		Tayside Contracts	SRMCS Score 40 /75
12	u/c	Kinnoull Street, Perth	Plane and Resurface HRA	315	3276	30.00	98280.00	248135.00		Tayside Contracts	SRMCS Very little data NIGHT WORKING - Mill St dependant
9	u/c	Old Edinburgh Rd Br of Earn	Plane off 50mm resurface taycoat	150	750	30.00	22500.00	270635.0		Tayside Contracts	SRMCS 2012 Data is Red over 100
11	u/c	Struan Rd/Strathtay to Forthingall	Plane & Resurface in Asphalt	940	6800	25.00	170000.00	440635.0		Tayside Contracts	SRMCS Score 40 /75
12	A93	Dunkeld Rd at St Catherine's junction	Plane and Resurface HRA		950	30.00	28500.00	469135.0		Tayside Contracts	SRMCS Score over 60 for Profile and Cracking
12	A93	Dunkeld Road and Barrack St,	Plane & resurface 40mm		6150	25.00	153750.00	622885.0		Tayside	SRMCS Score over 60 for Profile and

		Perth Crieff Road to Atholl St	OR Repave with patching HRA							Contracts	Cracking
8	A911	Easter Balgeddie-South of Kinneswood	Plane and Resurface HRA	1156	6936	25.00	173400.00	796285.0		Tayside Contracts	SRMCS Score 75 Crack / 59 for TEX
9	u/c	Kirkhall Rd Almondbank	Plane & Resurface in Taycoat	285	1425	20.00	28500.00	824785.0		Tayside Contracts	SRMCS Score 80 Crack / Profile
8	B918	Station Road, Kinross	Plane & Resurface in Taycoat		1285	20.00	25700.00	850485.0		Tayside Contracts	SRMCS Score 40 /75 High for Cracking
11	A85	Crieff Rd near College entrance	Plane and Resurface HRA	350	2100	25.00	52500.00	902985.0		Tayside Contracts	SRMCS Score over 80 for Profile and Cracking
8	A911	Kinneswood - Scotlandwell	Plane and Resurface HRA	1276	7656	25.00	191400.00	1094385.0		Tayside Contracts	SRMCS Score High for Profile and Cracking
12	A989	Atholl Street from Charlotte St to Kinnoull Street (incl Junction)	Plane and Resurface HRA	277	2900	25.00	72500.00	1166885.0		Tayside Contracts	SRMCS Score High for Profile and Cracking
12	A989	Atholl Street from Kinnoull Street to North Methven Street (incl Junction)	Plane and Resurface HRA	131	1370	25	34250	1201135			SRMCS Score High for Profile and Cracking
<b>2018/19 Onwards</b>											
9	C407	Main Street Almondbank	Plane/Resurface or Repave?			20.00	0.00		2019/20		Flood works ongoing
8	A91	Carnbo - Milnathort	Plane/Resurface or Repave?	1250	9375	25.00	234375.00	234375.0			
9	C407	West side of Bridge to Lumsden Cr	Plane and Resurface HRA	200	1700	25.00	42500.00	276875.0			Flood works ongoing
8	A911	Main street Scotlandwell	Plane and resurface HRA	480	3840	25.00	96000.00	372875.0			
12	A94	Pitcullen Cres Perth	Plane off 50mm resurface HRA	505	5050	25.00	126250.00	499125.0			



11	u/c	Geddes Drive, Perth	Plane & Resurface in Taycoat		1300	22.00	28600.00	527725.0			
6	A822	North Bridge St Crieff	Plane and Resurface HRA	347	2500	25.00	62500.00	590225.0			
12		Scott Street Perth	SMA replacement			25.00	0.00	590225.0			
8	B9097	vane farm section	Repave?			20.00	0.00	590225.0			
8	A823	Rumbling Bridge Village	HRA	890	7120	20.00	142400.00	732625.0			Carriageway breaking up
	A822	North of U1	Plane off & resurface	240	1440	25.00	36000.00	768625.0			
8	u/c	Green Road Kinross	Plane & resurface Taycoat			20.00	0.00	768625.0			Carriageway tired of patching
11	u/c	Goodlyburn Place, Perth	Plane and resurface. Minor footway.		1200	20.00	24000.00	792625.0			
12	u/c	King Edward Street, Perth	Plane and resurface.		550	25.00	13750.00	806375.0			
12	u/c	George Inn Lane, Perth	Plane and resurface.		160	20.00	3200.00	809575.0			
11	u/c	Balgowan Road, Perth	Plane and resurface.		1200	20.00	24000.00	833575.0			
11	u/c	Hermitage Drive, Perth	Plane and resurface.		2000	20.00	40000.00	873575.0			
7	A823	Castlehill Reservoir	Patch and SD ??			25.00	0.00	873575.0			
6	u/c	Lodge Brae/Burrell St.	Large patch??		966	25.00	24150.00	897725.0			Tracked uneven surface - recently patched

8	A977	Balado House to?????	Repave	1230	10086	20.00	201720.00	1099445.0			
7	B827	Dalginross Comrie	Plane and surface		2000	25.00	50000.00	1149445.0			
7	u/c	Langside Drive Comrie	Plane and surface		800	20.00	16000.00	1165445.0			
7	u/c	Leddoch Circle Comrie	Plane and surface		800	20.00	16000.00	1181445.0			
7	u/c	Eaglesfield Comrie	Plane and surface		800	20.00	16000.00	1197445.0			
10	u/c	Viewlands Road Perth	Plane and surface	830	5810	20.00	116200.00	1313645.0			Full length
7	A822	Drummond Street Muthill	Plane and surface				0.00	1313645.0			
12		Unity Terrace Perth	Plane and surface		1250	20.00	25000.00	1338645.0			Carriageway breaking up
<b>SURFACE DRESSING</b>											
9	C409	from B8063 to C409 Glenalmond junction	Surface Dressing	7400	7400	2.20	16280.00	16280.00	JMacK	Tayside Contracts	SRMCS Score 50-59 for TEX
9	C473	U6 Timber Haulage to C409	Surface Dressing	1850	7800	2.20	17160.00	33440.00	JMacK	Tayside Contracts	SRMCS Low score for TEX
9	U65	Dron Rd from A912 to C416 junction	Surface Dressing		3710	2.20	8162.00	41602.00	JMacK	Tayside Contracts	SRMCS Low score for TEX
6	A822	Bennybeg	Surface Dressing		8500	3.50	0.00	41602.00		Tayside Contracts	

8	U230	Solsgirth	Surface Dressing		2800	2.20	6160.00	47762.00	JMacK	Tayside Contracts	SRMCS score 39/75
8	U213	Muirhead - Easter Cottages	Surface Dressing		4200	2.20	9240.00	57002.00	JMacK	Tayside Contracts	SRMCS score 39/75
9	u/c	The Meadows	Surface Dressing				0.00	57002.00		Tayside Contracts	
6		Drummond Terrace, Crieff	Surface Dressing	370	1850	2.20	4070.00	61072.00	JMacK	Tayside Contracts	SRMCS Low score for TEX
8	B9097	B996 to West Brackley	Surface Dressing	850	6205	2.20	13651.00	74723.00	JMacK	Tayside Contracts	SRMCS score 39/75 Cracking
7	A822	Redford bends to Mlddleton	Surface Dressing	1790	11635	2.20	25597.00	100320.00	JMacK	Tayside Contracts	SRMCS Low score for TEX Higher score at Lodge of Orchil to Middleton
6		South Loch Earn (plus minor patching) Caravan Site west	Surface Dressing	6330	23205	2.20	51051.00	151371.00	JMacK	Tayside Contracts	SRMCS score 30/59 Cracking and Profile
8	B9097	Templeton to Carsegour	Surface Dressing	1600	9960	2.20	21912.00	173283.00	JMacK	Tayside Contracts	SRMCS score 30/39 Cracking Old overlay
7	U193	Middleton Road (A823-A822)	Surface Dressing	1660	6640	2.20	14608.00	187891.00	JMacK	Tayside Contracts	SRMCS score 75 for TEX at several locations
7		The Lurg (Previous overlay)	Surface Dressing	5510	22040	2.20	48488.00	236379.00	JMacK	Tayside Contracts	SRMCS score 75 for TEX at several locations
8	C413	Stronachie (Previous overlay)	Surface Dressing	8930	40185	2.20	88407.00	324786.00	JMacK	Tayside Contracts	SRMCS score 40/49 TEX Several overlay sections
7	B934	Bankhead Brae	Surface Dressing				0.00	324786.00			

7	U24	Whitemoss	Surface Dressing				0.00	324786.00			
7	U25	Coulshill	Surface Dressing				0.00	324786.00			
7	C471	Innerdunning	Surface Dressing	3400	13600	2.20	29920.00	354706.00	JMacK	Tayside Contracts	SRMCS Low score for TEX old overlay
6	B827	Langside Farm towards Braco along the top section still to do	Surface Dressing (Pre SD patching required)	3500	22050	2.20	0.00	354706.00			SRMCS score 75 for TEX at several locations and Profile / Cracking
11	u45	A85 to Ruthvenfield School	Surface Dressing	795	4375	2.20	9625.00	364331.00	JMacK	Tayside Contracts	SRMCS score 40/59 TEX Old overlay
6	u/c	Highlandman Loan A85 to Dowald	Surface Dressing	620	3720	2.20	8184.00	372515.00	JMacK	Tayside Contracts	SRMCS Low score for TEX
2	U154	Myreside road C401 to old Manse	Surface Dressing	500	2350	2.20	5170.00	377685.00	JMacK	Tayside Contracts	SRMCS Low score for TEX old overlay
2	C439	Kinrossie Village to the junction of C441	Surface Dressing		1500	2.20	3300.00	380985.00	JMacK	Tayside Contracts	SRMCS Score 40-59 for TEX
8	C420	Glenfarg - Milnathort north of Duncreevie	patch and SD	3000	14400	2.20	31680.00	412665.00	JMacK	Tayside Contracts	SRMCS Score 75 Profile at Duncreevie area
7	B934	Dunning to Wellhill	Surface Dressing	1 000	6000	2.20	13200.00	425865.00	JMacK	Tayside Contracts	SRMCS Score 40-75
7	B934	Drum of Garvock to Level Xing	Surface Dressing	1855	12057	2.20	26525.40	452390.40	JMacK	Tayside Contracts	SRMCS Score 40-75
1	C401	From Kinnaird road to Ballindean	Surface Dressing	900	4320	2.20	9504.00	461894.40	JMacK	Tayside Contracts	SRMCS Score 40-59 Rait to Easter Ballindean
8	B9097	Drum to Aldies	Surface Dressing	2600	15600	2.20	34320.00	496214.40	JMacK	Tayside Contracts	SRMCS Score 40-75 Profile and Cracking
7	U14	Lurg to Muthill	Surface Dressing	1981	7925	2.20	17435.00	513649.40	JMacK	Tayside Contracts	SRMCS Score low for TEX /80 Profile
7	U185	Mawbroons to U14	Surface Dressing	1828	7312	2.20	16086.40	529735.80	JMacK	Tayside Contracts	SRMCS Score low for TEX /80 Profile

7	C458	Tullibardine to Stratgeath	Surface Dressing	3775	22650	2.20	49830.00	579565.80	JMacK	Tayside Contracts	SRMCS Score 50-59 for TEX / 80 Profile
7	B8062	Pittenzie to Southwood	Surface Dressing	2836	17016	2.20	37435.20	617001.00	JMacK	Tayside Contracts	SRMCS Score 40-75
<b>2018/19 Onwards</b>											
1	U142	From C401 to Westown village	Surface Dressing	1.5k	7050	2.20	15510.00				SRMCS Score Low on section from Kinnaird to Westown
1	U142	Kinnaird rd from C401 to Abernyte	Surface Dressing	2000	9200	2.20	20240.00				SRMCS Score Low Small area at Gaurdswell
1	U83	From U80 to C401	Surface Dressing	3000	18400	2.20	40480.00				SRMCS Score Low Small area at Oliverburn
2	C405	Gask xrds to Balo woods	Surface Dressing	1500	4700	2.20	10340.00				SRMCS Score 20-49 North Ballo to Lochton
9	C418	From A913 up through hill section	Surface Dressing	1500	6000	2.20	13200.00				SRMCS Score 19-49 A913 to Bogles Quarry
9	U74	From A912 to junction	Surface Dressing	500	2200	2.20	4840.00				No SRMCS Data
7	B9141	From A9 to Station Road Dunning	Surface Dressing	3310	19860	2.20	43692.00				SRMCS Score 19-39 A9 to Dunning
7		Front of School Greenloaning	Surface Dressing	100	1000	2.20	2200.00				SRMCS Score low
2	U80	Balthayock rd from U83 to C404	Surface Dressing	2000	9000	2.20	19800.00				SRMCS Score 0-29
2	C404	Muirhall rd from Perth to U82	Surface Dressing	6000	28800	2.20	63360.00				SRMCS Score 0-49 Kinnoull to Deuchny Wood
2	U79	Ross rd from A90 to C484	Surface Dressing	1000	4500	2.20	9900.00				SRMCS Score low
2	U330	Flockloans rd from U143 to Angus boundary	Surface Dressing	800	2500	2.20	5500.00				SRMCS Score 19-49 Carmichaels Farm

2	U143	Flockloans rd from C403 to U330	Surface Dressing	900	3000	2.20	6600.00				SRMCS Score19-59 Cairn to Carmichaels Farm
2	C403	Knapp rd from Rossie ent to U142	Surface Dressing	6000	30000	2.20	66000.00				SRMCS Score19-49 Snabs to Knapp
1	C401	Teen Ranch to B953	Surface Dressing after overlay	1100	5280	2.20	11616.00				SRMCS Score19-49 at New Mains
6	B8033	Feddal Road	Surface Dressing	5645	33870	2.20	74514.00				
9	B9112	from Neccessity to B934 Jnc	Surface Dressing								
9	B935	Forteviot to Forgandenny	Surface dressing								
8	U222	From A977 to A91	Surface dressing								
8	U229	Arlary-Mawcarse	Surface dressing								
9	Zc412	Invermay to Jnc B996	Surface Dressing								
9	Zu52	Invermay	Surface Dressing								
9	Zu54	Ardargie- Culteuchar	Surface Dressing								
8	ZC415	New mill Farm - Path of condie	Surface dressing								
9	Zu228	Bankhead	Surface Dressing								
9	Zc420	Blairnathort-B996 JNC	Surface Dressing								
<b>Remedial Earthworks</b>											
6	B827	Langside rd	2 section gabion wall				12000.00	12000.0	DT	Tayside Contracts	
8	B9097	Broomhill Farm	Wall/gabions				35000.00	47000.0	DT	Tayside Contracts	

7		South Lochearn	Rock armour				10000.00	57000.0	DT	Tayside Contracts	
6	u199	Glenlednock	Gabion section	10m			4000.00	61000.0	DT	Tayside Contracts	
7	B934	Dunning Glen at Earnieside	Gabion section	15m			6000.00	67000.0	DT	Tayside Contracts	
<b>Repairs to retaining walls</b>											
12	u/c	Manse Road (right hand side - at footway)	Height extension to pre-cast unit wall (yellow)			112.06		20000.0	DT	External	Requires design/patent pre-cast blocks
<b>Drainage</b>											
9	A912	Glenfarg House-old quarry	renew drainfill				20000.00	20000.00	ARMO		
10	A912	Edinburgh Rd - Gleneagles to Friarton	Investigation and Install Drain				20000.00	40000.00	ARMO		
9	u/c	The Meadows B of E	investigation and soakaway replacement				10000.00	50000.00	ARMO		
8	B9097	Aldies to Poultry Farm	New pipe/drain fill and side entry gullies				52000.00	102000.00	JMacK		
9	A912	Main Street, Bridge of Earn	Investigation possible new drain outfall at Earn Bridge				20000.00	122000.00	DT		
8	A911	Wester to Easter Balgeddie	Install side entry gullies				0.00	122000			farmer resolved issue
12	A93	County Place south side	Install Acco drainage system				20000.00		ARMO		
8	B996	Mawcarse-Milnathort	new pipe /piped offlets								
	A824	Aberuthven-Auchterarder	Improve Drainage								
	A823	A822-Gleneagles	Improve drainage								
<b>Patching and reinstatements (recurring)</b>											

11	u/c	Kinnoull Causeway	40mm HRA patching plus drainage		300	17.50	5250.00	5250.0			
6	B8062	Highlandman to Crieff	40mm Taycoat patching			17.50	0.00	5250.0			SSE Beaully to Denny outside contractor
6	U12	Bennybeg to Muthil	40mm Taycoat patching			17.50	0.00	5250.0			
7	uc	Pirnhill	40mm Taycoat patching			12.50	0.00	5250.0			SSE Beaully to Denny outside contractor
7	B8033	Feddal	40mm Taycoat patching			17.50	0.00	5250.0			SSE Beaully to Denny outside contractor
6	A822	Garrick	40mm HRA patching		170	17.50	2975.00	8225.0			SSE Beaully to Denny outside contractor
	U190	Ochtermuthill area	40mm Taycoat patching			17.50	0.00	8225.0			
	C461	Muthil to Ochtermuthil	40mm Taycoat patching			17.50	0.00	8225.0			
	C467	Braco to Gleneagles	40mm Taycoat patching			17.50	0.00	8225.0			
	U188	Panholes	40mm Taycoat patching			17.50	0.00	8225.0			
7	A823	Frandy to Glendevon village	40mm HRA			17.50	0.00	8225.0			
	A823	Gleneagles to A822	40mm HRA patching			17.50	0.00	8225.0			
	C463	Meeniburn Road	40mm Taycoat patching			17.50	0.00	8225.0			
	u/c	Canal St/Charterhouse lane	40mm HRA patching			17.50	0.00	8225.0			
	C455	South Comrie Rd	40mm Taycoat patching			17.50	0.00	8225.0			
7	u/c	Glenburn Rd, Auchterarder	40mm HRA			17.50	0.00	8225.0			



7	u/c	Sydney Crescent, Auchterarder	40mm HRA			17.50	0.00	8225.0			
7	u/c	Southlands Road, Auchterarder	40mm HRA			17.50	0.00	8225.0			
7	u/c	Rossie Place, Auchterarder	40mm HRA			17.50	0.00	8225.0			
7	u/c	Victoria Road, Auchterarder	40mm HRA				0.00	8225.0			
	U/C	Ruthven Street	40mm HRA				0.00	8225.0			
<b>2018/19 Onwards</b>											
10 & 11	u/c	Western Edge	40mm HRA		1000	17.74	17740.00	17740.0		Tayside Contracts	5 Days Priority Order 3
6	u/c	Crieff Burgh	40mm HRA		2000	17.74	35480.00	53220.0		Competition	
12	u/c	Perth City Centre Inner Ring	HRA		2500	17.74	44350.00	97570.0		Competition	
9	C410	Abercairney to Crieff					0.00	97570.0		Tayside Contracts	10 Days Priority Order 9
9	various	Almondbank various					0.00	97570.0		Tayside Contracts	Suspended as flood works on-going
U/C	Tay Street Perth					0.00	97570.0			Competition	
u/c	Newhouse Rd to Rannoch Rd	Patch HRA				0.00	97570.0			Tayside Contracts	5 Days Priority Order 10
u/c	King Street at York Place where collapsed	Patch HRA				0.00	97570.0			Tayside Contracts	investigation required first
9	B935	Forgandenny - Forteviot	Pre SD		1000	17.74	17740.00	17740.0		Tayside Contracts	10 Days Priority Order 2
9	B934	Forteviot to Dunning	40mm HRA			17.74	0.00	17740.0		Tayside Contracts	20 Days Priority Order 1

7	B8062	Shinafoot-Dunning	HRA		1000	25.00	25000.00	42740.0		Tayside Contracts	5 Days Priority Order 5
7	B9112	Necessity Brae - Junction B934	40mm Taycoat		1000	17.29	17290.00	60030.0		Tayside Contracts	10 Days Priority Order 4
8	A977	Drum	HRA		1500	25.00	37500.00			Tayside Contracts	Registered for 08/05/17
8	A911	various sections	HRA				0.00	60030.0		Competition	
8	A91	M90-Carnbo	HRA				0.00	60030.0		Competition	
8	U222	A977-A91	40mm Taycoat		3000	17.29	51870.00	111900.0		Tayside Contracts	Registered for 11/05/17
7	B934	from B9112-Dunning	HRA		1000		0.00	111900.0		Competition	
8	B920	From B9097-Ballingry	HRA some pre SD				0.00	111900.0		Competition	
8	B920	Main Street Scotlandwell-C500	HRA				0.00	111900.0		Competition	
7	Zu26	Duchally	Taycoat Patching				0.00	111900.0		Competition	
8	B9097	From B920 to Boundry	HRA (Repave?)			22.00	0.00	111900.0		Tayside Contracts	5 Days Priority Order 6
8	C498	Gairneybank Full Length	Taycoat Patching			17.29	0.00	111900.0			
8	U225	Hatchbank	Taycoat Patching			17.29	0.00	111900.0			
	A91	B918 to Carnbo	HRA		1500	17.74	26610.00	138510.0		Tayside Contracts	10 Days Priority Order 8
8	B996	Kinross-boundary (various)	Taycoat		3000	17.29	8				
8	u/c	Green Road at Emslie	Taycoat		1500	17.29	8				
8	Zc415	New mill farm - Path of Condie	Taycoat		2000	17.29	8				
9	Zc412	Invermay to Junction B996	pre surf dress patching				9				
9	Zu52	Invermay	pre surf dress patching		800		9				

9	Zu54	Ardargie-Culteuchar	pre surf dress patching		1000		9				
8	ZC415	New mill Farm - Path of Condie	pre surf dress patching		1500		8				
9	Zu228	Bankhead	pre surf dress patching		1000		9				
9	Zc420	Blairnathort-B996 JNC	pre surf dress patching		1000		9				
1	B953	Inchture from 30mph to church	Kerbing and 40mm patching Taycoat		400	17.54	7016.00			Competition	
9	A93	From Main st Perth to U87	40mm hra patching		8000	17.54	140320.00			Competition	
2	C484	From St Madoes to Leetown	40mm hra patching		1000	17.54	17540.00			Tayside Contracts	10 Days Priority Order 7
2	A85	Invergowrie Main Street	40mm hra patching		700	17.54	12278.00			Tayside Contracts	Completed
2	A94	Scone to Balbeggie	Sporadic carriageway 40mm HRA		1000	17.54	17540.00	17540.0		Tayside Contracts	
2	A94	Pitcullen Cres to 40mph	40mm hra patching		700	17.54	12278.00	29818.0		Competition	
2	C441	From A94 to Collace	40mm Taycoat		1800	17.54	31572.00	61390.0		Tayside Contracts	
CAPITAL FOOTWAY SURFACING/OVERLAY 2017/18											
12	u/c	Kinnoull Street, Perth (Let's Eat)	Reconstruct slabbed footways		290	17.54	5086.60	5086.60		Tayside Contracts	School holidays
1	u/c	Pitfour St Madoes	Req reconstruction and kerbing	560	1120	17.54	19644.80	24731.40		Tayside Contracts	
8	B996	Hatchbank houses to bus stop on east side	Resurface footways		150	17.54	2631.00	27362.40		Tayside Contracts	
1	u/c	Greystane Rd Invergowrie Full Length	Footway resurface		800	17.54	14032.00	41394.40		Tayside Contracts	
12	A93	South St Old post office to King Edward street	Reconstruct slabbed footways	135	580	86.00	49880.00	91274.40		Tayside Contracts	
11	u/c	Commercial Street Perth	Footway resurface	200	400	17.54	7016.00	98290.40		Tayside Contracts	

8	u/c	Hayfield road Glenfarg	Resurface Footway / Kerb	150	180	25.00	4500.00	102790.40		Tayside Contracts	
10	u/c	Glenearn Road	Kerbing / Resurface	450	900	17.54	15786.00	118576.40		Tayside Contracts	
8	B918	Station Road, Kinross (Tayset)	Resurface Footway	1550	2170	17.54	38061.80	156638.20		Tayside Contracts	
2	u/c	Red Cliffs Kingoodie	Resurface to footways		400	17.54	7016.00	163654.20		Tayside Contracts	
10	u/c	Cedar Drive Perth (south side)	HRA 75mm	1000	1400	17.54	24556.00	188210.20		Tayside Contracts	
2	A94	Perth Rd Scone, Cross st / flats	HRA 75mm	400	720	17.54	12628.80	200839.00		Tayside Contracts	
12	A93	King Street to Newrow	HRA 75mm	90	252	17.54	4420.08	205259.08		Tayside Contracts	
12	u/c	Lewis Place, Perth	Resurface & re- kerb		1100	17.54					
12	u/c	King Edward Street, Perth (South St - Sth St John's Place)	Reconstruct slabbed footways		450	17.54					
12	u/c	George Inn Lane, Perth	Reconstruct concrete footway & re-kerb.		140	17.54					
12	u/c	Atholl Street, Perth (Kinnoull St - Nth Methven St)	Plane & resurface		600	17.54					
12	u/c	Atholl Street, Perth (Charlotte PI - Kinnoull St)	Reconstruct slabbed footways		650	17.54					
12	u/c	Charlotte Street, Perth (both sides)	Reconstruct slabbed footways		400	17.54					
12	u/c	George Street, Perth (west side)	Reconstruct slabbed footways		500	17.54					
12	u/c	Murray Street, Perth (north side)	Reconstruct slabbed footways		220	17.54					
12	u/c	Watergate	Resurface		360	17.54					

12	A85	Perth Bridge footways	Resurface Footway			17.54					
12	u/c	High St bottom end	kerbing and reconstruct slabbed footways		500	17.54					
2	u/c	Dupplin rd Perth	Resurface to footways		600	17.54					
2	u/c	Kings Mason Kingoodie	Resurface to footways		300	17.54					
2	A94	Perth Rd Scone, Cross street / flats	HRA 75mm		300	17.54					
	A93	York Place Perth	Taycoat 75mm		300	17.54					
FOOTWAY WORKS - Slurry Seal 2017/18											
8	A911	Main Street Kinneswood	Slurry Seal		650	6.00	3900.00	3900.00	RMP	Tayside Contracts	
10		Pitheavles Terrace	Slurry Seal	520	1100	6.00	6600.00	10500.00	RMP	Tayside Contracts	
6	u/c	Drummond Av Auchterarder	Slurry Seal	422	676	6.00	4056.00	4056.00	RMP	Tayside Contracts	
6	u/c	Grampian Av Auchterarder	Slurry Seal	1150	1725	6.00	10350.00	14406.00	RMP	Tayside Contracts	
7	u/c	Strathview Pl Comrie	Slurry Seal	530	795	6.00	4770.00	19176.00	RMP	Tayside Contracts	
10	u/c	Glenfarg terr	Slurry Seal	324	486	6.00	2916.00	22092.00	RMP	Tayside Contracts	
10	u/c	Glenshee cres	Slurry Seal	280	392	6.00	2352.00	24444.00	RMP	Tayside Contracts	
10	u/c	Glenbruar cres	Slurry Seal	252	353	6.00	2118.00	26562.00	RMP	Tayside Contracts	
10	u/c	Glenogle cres	Slurry Seal	255	357	6.00	2142.00	28704.00	RMP	Tayside Contracts	
9	u/c	Lumsden Crescent	Slurry Seal	620	868	6.00	5208.00	33912.00	RMP	Tayside Contracts	
2	u/c	Stormont road Scone	Slurry seal	400	1000	6.00	6000.00	39912.00	RMP	Tayside Contracts	

2	u/c	Spoutwells Scone various locations	Slurry seal	300	600	6.00	3600.00	43512.00	RMP	Tayside Contracts	
7	u/c	Allanbank Crescent Greenloaning	Slurry seal	640	1155	6.00	6930.00	50442.00	RMP	Tayside Contracts	
<b>2018/19 Onwards</b>											
8	U/C	Greenpark Kinross	Slurry Seal								
7		Commanders Grove Braco	Slurry Seal								
10		Poplar Cres Perth	Slurry Seal								Co-Op to Poplar Place east side
6		Glenorchil View Auchterarder	Slurry Seal								
7		Glebe Road Comrie	Slurry Seal								
10		Elm Gardens Perth	Slurry Seal								
12		Marshall Place Perth	Slurry Seal								Shore Rd-Princess Street
10		Broomhill Drive Perth	Slurry Seal								
11		Muircroft Terrace Perth	Slurry Seal								
12		Princess Street Perth	Slurry Seal								Canal Street- Marshall Place west side
2	A85	Dundee Road Perth	Slurry Seal								
12		Kings Place Perth	Slurry seal								North side King Street to Railway Station

NORTH AREA											
WARD	ROUTE	LOCATION- FROM/TO	DESCRIPTION	LENGTH	AREA	RATE	COST	CUM TOTAL	Designer	Contractor	Comments

Revenue budget £695,000											
REVENUE - Cyclic											
Gully cleaning											
var	var	clean all gullies on 1 occasion	15000 gullies (including traffic control sites)				120.0	130.0	RMP	Tayside Contracts	routine cleaning - 1 cycle and adhoc
var	var	jetting and cleaning pipes as required					20.0	140.0	RMP	Tayside Contracts	clear blocked gullies following routine clean
Sweeping and cleaning											
var	var	as required					2.0	142.0	RMP	Tayside Contracts	for safety
REVENUE -Routine											
Reactive patching											
var	var	as required					291.6	433.6	RMP	Tayside Contracts	
var	var	OOH service					36.0	469.6	RMP	Tayside Contracts	
Drainage- ditches and offlets											
var	var	ditching and offlets					100.0	569.6	RMP	Tayside Contracts	
Road Markings											
var	var	renew junction markings					20.0	589.6	RMP	Tayside Contracts	
var	var	renew longitudinal road markings					55.0	644.6	RMP	Competition	
Other Routine											
var	var	as required					45.0	689.6	RMP	Tayside Contracts	
Flood Defences £6000											
var	var	flood alleviation	weem and caputh pumps				6.0	695.6	RMP	Ritchie MacKenzie/EDF	
Capital											
RECONSTRUCT FAILED CARRIAGEWAY											
2017-18											
5	Unc	Planton Square Luncarty	Reconstruct road and footway		191	100.00	44.0	44.0		Tayside Contracts	Surface failure Housing Stock see

											also footways
4	B8019	Garry Bridge west wards	Reconstruct road	200	1200	100.00	120.0	164.0		Tayside Contracts	Surface in poor condition, deformation and extensive cracking
4	U169	Old Blair Road Lodge to Chinese Gardens	Tay- Dress	520	2735	14.62	40.0	204.0		Tayside Contracts	Surface Failure badly deteriorated in wheel track
4	C452	Foss Road The lick to Duntanlich	Re-tread and surface dress.	2300	6928	12.99	90.0	294.0		Competition	100 colas reminder TC
<b>2018-19</b>											
2	U92	Junction U91 to Drumore Cottages	Re-tread carriageway	1000	3500	14.00	49.0	49.0			Surface failure more than a 1/3 of the road surface
5	Unc	U173 Glen Quaich	Re-tread and Surface dress	2579	9026	14	126.4	126.4			Surface failure
5	U35	Garry Cottage Eastwards	Re-tread and surface dress. With short section of overlay	1250	3750	14.00	52.5	52.5			Surface affected with ponding water
<b>2019-20</b>											
4	C448	Wester Camunvrachen to 600m to the west	Re-tread and Surface dress	700	2450	14.00	34.3	34.3			Short section of road requires strengthen prior to re-tread
5	C429	Junction A923 to Catchpenny	Re-tread and Surface dress	2784	12525	14.00	175.4	209.0			Single course overlay and fretting, with narrow verges and ditches
<b>2020-21</b>											
4	C448	700m West of Wester Invervar for a distance of 600 m	Re-tread and Surface dress	600	2400	14.00	33.6	33.6			
4	U169	Monzie between cattle grids	Re-tread and surface dress.	1550	4650	14.00	65.1	98.7			Surface failure out with recent patching
<b>OVERLAY CARRIAGEWAY</b>											
<b>2017-18</b>											



4	B846	Dunan to Gaur Power Station	DBM Resurface carriageway	1060	4240	28.00	118.7	118.7		Tayside Contracts	Surface failure
4	B846	Junction B8019 to Dalno Bridge	DBM overlay	150	2610	29.45	76.9	195.6		Tayside Contracts	
5	A923	Waterhouse to golf course Access	Overlay carriageway, including completion of drainage.	530	2915	40.00	116.6	312.2		Tayside Contracts	
2	A93	Riedorroch to recent overlay	Overlay carriageway	1535	8442.5	28.00	236.4	548.6		Competition	Surface in poor condition
2	A93	Pottery to let in joint	Overlay carriageway	275	1787.5	30.00	53.6	602.2		Competition	Surface deformation and cracking
4	U174	Dull West junction to Cross	Overlay carriageway	600	1620	35.00	56.7	658.9		Tayside Contracts	Surface in poor condition
<b>2018-19</b>											
3	A93	Recent overlay to Bridge of Cally	Overlay carriageway	475	2850	28	79.8	79.8			Failed surface
5	A822	Inver Branch Road to Ladywell Cottage	Overlay carriageway	1125	5850	28.00	163.8	243.6			Surface in poor condition
5	U35	Garry Place to Bridge	Overlay carriageway	230	690	28.00	19.3	262.9			Surface in poor condition
5	U113	Nethermuir	Overlay carriageway	90	315	28.00	8.8	271.7			Surface in poor condition
5	U35	Nerther Obney to Upper Obney	Overlay carriageway	905	2715	28.00	76.0	347.8			Surface in poor condition
4	Unc	Dalnasphalt of A9	Thin Surfacing	55	275	9.24	2.5	350.3			On hold pending A9 duelling details
5	C419	Broomhill junction westwards	Overlay	230	920	28.00	25.8	376.1			Surface ponding with water requires lifted and shaped
4	Unc	The Terrace, St Andrew St Blair Atholl	Overlay carriageway	600	3000	36.46	109.4	485.4			Surface in poor condition
5	C430	Junction C429 to C428	Overlay carriageway	679	3734.5	36.46	136.2	621.6			Single course overlay
4	C454	Junction A9 to Accommodation access	Thin Surfacing	215	1397	36.46	50.9	672.5			Surface failure in poor condition

2019-20											
5	Unc	Shielhill Place Stanley	Thin Surfacing	222	1376.4	9.24	12.7	12.7			Surface starting to deteriorate
5	unc	Russel St Stanley	Thin Surfacing	195	819	8.82	7.2	19.9			Surface worn
5	U35	Bridge Westwards	Overlay carriageway	440	1320	28.00	37.0	56.9			Surface in poor condition
4	B846	Weem Toll House to Weem Church	Overlay carriageway	550	2750	36.46	100.3	157.2			Old patches from utility presence
4	C451	Skiag to Kepranich	Overlay carriageway	1000	4000	36.46	145.8	303.0			Surface deformation of road surface and potholes
4	unc	Higher Oakfield Pitlochry	Thin Surfacing	250	1625	9.24	15.0	318.0			Surface in fair condition
2	Unc	Armadale Cres Balbeggie	Plane off and resurface	137	434	36.46	15.8	333.8			Surface in fair order
5	unc	Athole Drive Stanley	Thin Surfacing	230	1380	8.82	12.2	346.0			Surface flat minor area of ponding water
5	C504	Perth road Birnam	Thin Surfacing	877	5704	9.24	52.7	398.7			Surface flat minor area of ponding water
5	Unc	Murray Place Stanley	Thin Surfacing	312	1466	8.82	12.9	411.7			Preventative maintenance
5	U33	Prieston road Bankfoot	Thin Surfacing	555	3052	9.24	28.2	439.9			Surface in good condition
4	unc	Braeside Road Ballinluig	Thin Surfacing		2742	9.24	25.3	465.2			Surface in good condition
4	unc	Buail Bhan Ballinluig	Thin Surfacing		858	9.24	7.9	473.1			Surface in good condition
PLANE OFF EXISTING SURFACE AND RESURFACE CARRIAGEWAY											
2017-18											
4	A827	The Square Aberfeldy	Plane of and resurface	65	520	42.00	21.8	21.8		Competition	Surface deteriorating Hold until Aberfeldy place check
4	A827	Kenmore Bridge	Plane of and resurface	250	1375	38.00	52.3	74.1		Tayside Contracts	Surface cracking and potholing
2	Unc	Losset Road Alyth Junction	Plane off and resurface with	140	560	38.00	21.3	95.4		Tayside	Surface in poor condition with areas

		with Toutie St to Parkside Road	DBM							Contracts	of ponding water. Surface failure throughout section
4	unc	Moness Terrace Aberfeldy	Plane off and resurface	160	1200	38.00	45.6	141.0		Tayside Contracts	Extensive cracking and potholes forming throughout section of road. Road adjacent to shopping area surface through junction uneven and extensive cracking and potholing
4	u/c	Taymouth Drive Kenmore	Plane off and resurface	213	1065	38.00	40.5	181.4		Tayside Contracts	Access to school surface failure
4	unc	Chapel street, aberfeldy	Plane off and resurface	100	600	38.00	22.8	204.2		Tayside Contracts	Surface failure
<b>2018-19</b>											
3	A93	Balmoral Road Rattray.Hatton road Craighall	Overlay carriageway	527	3430	38.00	130.3	130.3		Tayside Contracts	Section added to Capital plan for re-alignment
4	unc	Home Street Aberfeldy	Plane off and resurface	200	1400	38.00	53.2	183.5			Extensive reflective cracking
2	Unc	Wylies Brae Alyth	Plane of and resurface	84	504	28.00	14.1	197.6			Surface failure
4	U/c	Allt Mohr Crescent Kinloch Rannoch	Plane off and resurface	65	300	38.00	11.4	209.0			Surface temporary patched since last inspection
4	Unc	Appin Place Aberfeldy	Plane off and resurface	100	800	38.00	30.4	239.4			Surface in poor condition
3	Unc	James St Blairgowrie	Plane off and Resurface	121	1354	36.45	49.4	288.8			Surface reflective cracking
4	unc	Taybridge Drive, Aberfeldy	Plane off and resurface	365	2550	38.00	96.9	385.7			Seal crazed but not deformed surface
4	unc	Alma Avenue, Aberfeldy From A827 to bend near school car park	Resurface carriageway - 100mm with HRA surface	185	1200	38.00	45.6	431.3			Further deterioration in surface
<b>2019-20</b>											

17	A94	Station Road Burnside Roundabout Coupar Angus	Plane off and resurface	137	753.5	38.00	28.6	28.6			Failure of HRA surface
3	u/c	Ferguson Park Road Rattray	Plane off and resurface	463	3560	38.00	135.3	163.9			Failure of HRA surface
4	Unc	East Moulin road No. 91 to West Moulin road	Plane off and resurface	210	1050	38.00	39.9	203.8			Reflective cracking throughout section
3	A926	5 Roads Caravan site to Surface Dressing	Plane off and resurface	422	2743	38.00	104.2	308.0			Reflective cracking throughout section
5	C504	Junction A923 to St Mary's road	Plane off and resurface	900	5850	38.00	222.3	530.3			Reflective cracking and fretting throughout section of road
<b>2020-21</b>											
5	Unc	Marshal Way Luncarty from Westfield to Millar road	Plane of and resurface	550	3300	38.18	126.0	126.0			Surface worn and uneven
5	A923	Dunkeld Bridge	Plane off and surface	230	1210	38.18	46.2	172.2			Surface potholes and crazing
2	A94	A94 High St Burrelton	Plane off and resurface	440	3300	38.00	125.4	297.6			Failure of thin coat surfacing
3	A923	Dunkeld Road. Perth road to 400 m west	Plane off and resurface	410	2788	38.00	105.9	403.5			Surface worn and deformation occurring
2	A923	Queen St Coupar Angus	Plane off and resurface	414	1629	38.00	61.9	465.4			Failure of surface
<b>2021-22</b>											
3	A93	Junction A924 to Junction U94 Drimmie Road	Plane off and resurface	450	2457	38.00	93.4	93.4			Failed surface dressing site
4	unc	Moness Crescent Old Crieff road to Old Crieff Road	Plane off and resurface	750	3750	38.00	142.5	235.9			Surface patched 2014
4	Unc	Ford Road Blair Atholl	Plane of and resurface	156	650	38.18	24.8	260.7			Surface failure

4	Unc	Main Road Ballinluig Filling Station to St Cedds	Plane off and resurface	415	3112.5	38.00	118.3	379.0			Surface cracking and potholed extensive patching required
3	A926	Old Rattray Cross	Resurface carriageway with HRA	375	2438	38.00	92.6	471.6			Worn Surface
<b>2022-23</b>											
4	A827	Pitnacree Bridge	Plane bridge Surface and overlay	80	400	38.00	15.2	15.2			Surface in poor condition with areas of ponding water
5	B9099	A984 to 30 mph Caputh	Plane of and resurface	286	2100	27.89	58.6	73.8			No change
4	Unc	Old Crieff Road aberfeldy	Plane of and resurface	200	1000	38.18	38.2	111.9			Surface cracking
2	A94	Old Toll House to Langlogie Farm	Resurface carriageway with HRA	650	4875	45.15	220.1	332.1			Deformation in wheel track
	U/C	Upper Allan Street Blairgowrie. High Street to Burnhead Road	Plane off and resurface	450	2475	38.00	94.1	426.1			Surface worn polished
5	U115	Gormack Bridge to Westerton Farm	Resurface		455	27.89	12.7	438.8			Surface worn and deformation occurring
3	U104	McDonald Crescent Rattray Between Haugh road and Ashgrove Road	Resurface carriageway and parking area with HRA	180	900	36.27	32.6	471.4			
3	unc	Park drive, Blairgowrie 2 cul de sac	Resurface carriageway and parking area with Taycoat	300	1800	27.89	50.2	521.6			
<b>2023-24</b>											
4	A923	70m West of C429 to 200m West of Drumbuie Cottage	Plane off and resurface	980	5684	38.00	216.0	216.0			Surface in poor condition with chip loss

4	A923	Junction C502 to Water house	Plane off and resurface	770	4158	38.00	158.0	374.0			Surface cracking investigation required into the stability of road edge near to Tigh Grainach
3	U/C	Kirk Wynd Blairgowrie	Plane off and resurface	330	1716	38.00	65.2	439.2			Surface potholed
	U/C	Upper Craighall Place	Plane off and resurface	180	882	38.00	33.5	472.7			Surface in fair condition
<b>Projects funded from £2M non-recurring budget.</b>											
<b>2017-18</b>											
3	A93	Perth Road. Reform St to Dunkeld Road Blairgowrie	Plane off and resurface	350	2450	40.00	98.0	98.0		Tayside Contracts	Surface worn and deformation occurring
	A93	Balmoral Road Rattray. Junction High Street to Hatton to road	Plane off and resurface	586	4100	36.00	147.6	245.6		Tayside Contracts	Surface area between High St Rattray Coralbank Road surface requires reconstructive patching
4	A826	Crieff Road Aberfeldy	Plane of and resurface	500	2750	33.00	90.8	336.4		Competition	Improve running surface
<b>SURFACE DRESSING</b>											
<b>2017-18</b>											
var	var	prep work for surface dressing	Edging				22.0	22.0		Tayside Contracts	
var	var	road markings and studs following surface dressing					45.0	67.0		Competition	
2	A926	Roundabout to Angus Boundary	Surface Dress	1450	8700	2.80	24.4	91.4		Competition	Surface fretting and chip loss
5	U40	U40 Linn road Stanley	Surface Dressing	1645	5408	2.20	11.9	103.3		Competition	Preventative maintenance
5	Unc	Store Street Stanley	Surface Dressing	193	2026	2.20	4.5	107.7		Competition	Preventative maintenance

5	Unc	Percy Street Stanley	Surface Dressing	134	1072	2.20	2.4	110.1		Competition	Preventative maintenance
5	Unc	Mill Street Stanley	Surface Dressing	1000	6000	2.20	13.2	123.3		Competition	Preventative maintenance
5	Unc	King St Stanley	Surface Dressing	340	3128	2.20	6.9	130.2		Competition	Preventative maintenance
5	U38	Duchess Street Stanley	Surface Dressing	650	4875	2.20	10.7	140.9		Competition	Preventative maintenance
2	A94	Balbrogie road end to Denhead Farm	Surface Dress	720	5256	2.80	14.7	155.6		Competition	Minor area patching and chip loss
2	A94	Wester Denhead to 30mph Coupar Angus	Surface dressing	1543	10804	2.80	30.3	185.8		Competition	
2	A94	Coupar Angus to Denhead Farm	Surface Dress	1480	10804	2.80	30.3	216.1		Competition	Minor area patching and chip loss
	U/104	Old Mill Road to End	Surface Dressing	1685	5055	2.20	11.1	227.2		Competition	Patching with two overlay patches required
5	A984	Main Street Spittalfield	Surface Dressing	502	3012	2.80	8.4	235.7		Competition	Reflective cracking and fretting throughout section
4	B847	A9 Junction to Calvine	Surface Dressing	450	2790	2.20	6.1	241.8		Competition	Access of A9 surface very worn
5	A984	Main Street Meikleour	Surface Dressing	490	2940	2.80	8.2	250.0		Competition	Planner patching require prior to dressing
4	B846	Dunalastair Brae top of hill to Trim Cottage	Surface Dressing	1700	9180	2.80	25.7	275.7		Competition	Failed surface dressing, overlay patch require prior to surface dressing
4	U164	Balchandy to Tulliemet Junction	Surface dressing	3500	12250	2.20	27.0	302.7		Competition	Old surface dressing failed centre of road affected with frost heave and patching beginning to fret.
4	A827	Junction C451 to Fort Lodge	Surface Dressing	1850	9620	2.80	26.9	329.6		Competition	Reflective cracking throughout section. Patching required prior to surface dressing

3	U94	Kynballoch	Surface Dressing	3840	16128	2.20	35.5	365.1		Competition	Overlay needing to be sealed.
5	U116	Pittensorn	Surface Dressing	4603	23015	2.20	50.6	415.7		Competition	
4	U178	Claggan Road	Surface Dressing	1375	3850	2.20	8.5	424.2		Competition	Preventive maintenance
4	A827	Bolfracks to Aberfeldy	Retexture fatted dressing	3	day	2400.00	7.2	431.4		Competition	Surface requires retextured worn and excess bitumen in the wheel track
4	B846	Tirine Farm to Coshieville	Retexture fatted dressing	2	day	2400.00	4.8	436.2		Competition	Surface requires retextured worn and excess bitumen in the wheel track
2	C423	Boat of Bardmoney to Junction A926	Retexture fatted dressing	2	day	2400.00	4.8	441.0		Competition	Surface heavy with bitumen consider high pressure cleaning / retexturing
3	A923	Coupar Angus Road, Blairgowrie. Emma St to Golf Course road	Retexture fatted dressing	3	day	2400.00	7.2	448.2		Competition	Surface reflective cracking chip loss and old dressing polished

**2018-19**

4	B846	East of Kinloch Rannoch Picnic are to Drumcastle Farm	Surface Dressing	1500	7950	3.75	29.8	29.8			Failed surface dressing, overlay patch require prior to surface dressing. Areas of patching required
2	C438	Junction C437 to A93	Surface dressing	2821	16224	2.20	35.7	65.5		Competition	Surface worn
2	C437	Milestone Farm junction C438	Surface Dress	2000	9400	2.20	20.7	86.2		Competition	Surface worn
2	unc	Belmont Place	Surface Dressing	138	728	2.25	1.6	87.8			Surface worn
3	U108	Welton Road, Surface dressing to junction U107	Surface Dressing	2374	9496	2.50	23.7	111.6			Minor patching require with recent overlay requiring sealed



4	B847	Auchleeks to Kinaldy	Surface Dressing	3980	18308	2.50	45.8	157.3			Surface requires retextured worn and excess bitumen in the wheel track minor patching and reflective cracking on surface
4	B847	Balmore Junction to Mullinavdie access	Surface Dressing	2900	13630	2.50	34.1	191.4			Surface requires retextured worn and excess bitumen in the wheel track minor patching and reflective cracking on surface
4	B847	C453 Bohespik Junction to 1376 m South	Surface Dressing	1376	6468	3.75	24.3	215.7			Old surface minor areas Patching reflective cracking, minor drainage is require to prevent water running over road
5	A822	South side of Trochry to Junction Rumbling Bridge	Surface Dressing	2117	11008	3.75	41.3	256.9			Surface polished and failures in old dressing
5	A822	Amulree to Junction A826	Surface Dressing	2800	14560	3.75	54.6	311.5			Surface polished and heavy with bitumen
5	A822	Meikle Tombane to South side of Trochry	Surface Dressing	1528	7997.6	3.75	30.0	341.5			Surface in poor condition
4	A826	A822 to access Griffin Wind farm	Surface Dressing	4358	24840	3.75	93.2	434.7			Previous surface dressing failed patching carried out 2016
5	A923	Golf Club access to C429	Surface Dressing	770	4158	3.75	15.6	450.3			Surface polished
4	A923	Carney Bridge to Butterstone	Surface Dressing	990	5346	3.75	20.0	470.3			Old surface dressing stripping leaving areas polished
3	A93	Old Scone t 0 Balboughty	Surface Dressing	1600	12000	3.75	45.0	515.3			PMS site old dressing stripping

		Cottages									
3	A93	Berry Shop Scones of Lethendy to Barclayhill House	Surface Dressing	1440	9360	3.75	35.1	550.4			Anti-skid in good order patching required with area of dressing stripping
3	A93	Balboughty Cottages to Berry Shop Scones of Lethendy	Surface Dressing	670	4355	3.75	16.3	566.8			Patching required and dressing stripping and chip loss on asphalt surface
<b>2019-20</b>											
3	A93	Junction with Campsie to Burnside cottages	Surface Dressing	2550	16575	3.75	62.2	62.2			Reflective cracking to the east of recent overlay patching carried out during 2016
3	A93	Guildtown to North Byres Farm	Surface Dressing	950	6175	3.75	23.2	85.3			Preventive maintenance on recent patching and overlay and reseal failed dressing
2	C423	Boat of Bardmoney to Cronan	Surface Dress	1312	4592	2.50	11.5	96.8			Surface requires sealed following recent overlay
3	unc	Shaw Street, Blairgowrie	Surface Dressing	120	660	2.50	1.7	98.4			Preventive maintenance
3	A93	Snow gates at Spittal of Glenshee to Allt an Charnaich Bridge	Surface Dressing	1900	10450	3.75	39.2	137.6			Surface in fair condition very low traffic
4	A827	Fort Lodge to East Lodge	Surface Dressing	2400	12480	3.75	46.8	184.4			Preventive Maintenance
4	A827	West of Fearnan to East of Fearnan	Surface Dressing	1560	7800	3.75	29.3	213.7			Preventive Maintenance
4	B846	100m West of Bomore junction to 100m east	Surface Dressing	200	1040	3.75	3.9	217.6			Preventive Maintenance
4	B846	Dalno Bridge to Bohespig Junctin	Surface Dressing	720	3816	3.75	14.3	231.9			Preventive Maintenance

5	A822	Ballachaggan to Meikle Tobane	Surface Dressing	2300	11960	3.75	44.9	276.7			Surfaced patched 2016 preventive maintenance
4	A826	Recent Surface dressing to 500m South of Calliachart	Surface Dressing	1844	10510	3.75	39.4	316.2			Preventive maintenance patching carried out 2016/17
5	A827	Eastertyer to Newton Farm	Surface Dressing	1100	5940	3.75	22.3	338.4			Preventative maintenance
5	A923	80m East of U114 to Junction C430	Surface Dressing	1350	7830	3.75	29.4	367.8			Preventative maintenance
4	A827	Pitnacrea Bridge to Eastertyer	Surface Dressing	2530	15180	3.75	56.9	424.7			
	U89	Junction A93 to Junction C434	Surface Dressing	2150	9675	2.50	24.2	448.9			surface in good order
4	B867	Main St Bankfoot	Surface dressing	796	6535	3.75	24.5	473.4			Reflective cracking and polished surface
4	U161	Ben Lawers Road	Surface Dressing	1300	5800	2.50	14.5	487.9			Reflective cracking to the east of recent overlay patching carried out during 2016
<b>2021-22</b>											
2	A94	Junction C439 to Auchmyre	Surface dressing	1529	10703	3.75	40.1				surface in good order
2	A94	Auchmyre to Balgay farm access	Surface dressing	863	9047	3.75	33.9				surface in good order
4	U181	Mains of Murthly	Surface Dressing	550	1650	2.50	4.1				Surface in fair condition very low traffic
5	Unc	East Brougham Street Stanley	Surface Dressing	250	1500	2.50	3.8				Surface in good condition
2	U101	Junction U100 to Angus Council Boundary	Surface Dress	215	8736	3.06	26.7				seal overlays
2	C436	Caddam Road Causewayend to North Lodge	Surface Dress	2340	9360	3.06	28.6				seal overlays

2	A924	Glen Fernate Bridge to Inverchorskie	Surface Dress	2000	11000	3.75	41.3				Surface overlaid during 2014/15 requires sealed
4	C450	Camghouran	Surface Dress	3500	10500	2.50	26.3				Surface patched 2015 preventive maintenance
4	C450	Kinloch Rannoch to Crossmount	Surface Dress	4000	16000	2.50	40.0				Surface patched 2015 preventive maintenance
4	C450	Dall Bridge to Carrie Bridge	Surface Dress	3200	9600	2.50	24.0				Surface patched 2015 preventive maintenance
4	B846	Bridge of Ericht	Surface Dress	200	1000	2.50	2.5				Surface patched 2015 preventive maintenance
4	B846	Leargan	Surface Dress	800	3200	2.50	8.0				Surface patched 2015 preventive maintenance
4	C447	Strathtay road	Surface Dress	3350	15400	2.50	38.5				Surface patched 2015 preventive maintenance
2	C16	A923 to Knollhead Farm	Surface Dress	1257	7013	2.50	17.5				Nimpacticote Surfaced recently. Footway requires reconstructed from Junction A923 to Kettins
4	B8019	Clunie Dam to Bonskied House	Surface Dressing	2200	10780	3.75	40.4				Patching carried out 2015 /16 Surface requires sealed small section of subsidence west of Fincastle
3	A924	Tarvie to Enochdhu	Surface Dressing	5221	30025	3.75	112.6				Preventive maintenance recent overlays and patching
4	U163	Ballinluig to A9 junction	Surface Dressing	7160	28640	2.50	71.6				Patching and overlays carried out 2016/17 Preventative

												maintenance
4	A827	A9 Road Bridge to Newton Farm	Surface Dressing	2090	12540	3.75	47.0					Preventative maintenance
5	A984	Dungathill to Old Surface dressing East of Dungarhill	Surface Dressing	994	5964	3.75	22.4					Surface dress recent overlay Preventive maintenance
5	U116	Junction B867 to junction B9099	Surface Dressing	4630	23150	2.50	57.9					Extensive patching carried out 2016 requires seal Preventive maintenance
	U104	Ashgrove terrace to Old Mill Road	Surface Dressing	470	2350	2.50	5.9					Surface in good order minor area of ponding water

**REMEDIAL EARTHWORKS**

**2017-18**

4	A827	Tir Artir	Repairs to collapsing verge - Sheet piling?	45		600.00	27.0	27.0		Tayside Contracts	Edge of road fallen away
5	U173	Near the Garrows	Retaining embankment at river Quaich	95		500.00	35.0	62.0		Tayside Contracts	
4	A827	500m west of alt beag	Repair eroded embankment			65.00	65.0	127.0		Tayside Contracts	
4	B8019	Bruach bhan	Gabions and retaining embankment	85		200.00	17.0	144.0		Tayside Contracts	
var	var	various locations as required	verge and embankment repairs				25.0	169.0		Tayside Contracts	small projects as required by supervisor throughout year

**2018-19**

5	A822	Trochry	Take down retaining wall (parapet section) form retaining embankment, drainage	85		750.00	63.8	63.8				safety railing damaged(has been for some time) cracks in road and subsidence in carriageway near wall
---	------	---------	--	----	--	--------	------	------	--	--	--	---

4	B8079	South of Bridge of Tilt (Craggan corner)	Form retaining embankment	40		750.00	30.0	93.8			Surface patched 2015/16 to remove depression in road surface
4	C451	East of Wester Tullich	Form retaining embankment	65		750	48.8	142.5			Verge and bank sunk and not support to road
4	C447	West of Cluny U175	construct gabbion structure to hold up road	40			40.0				road subsided
<b>Repairs to retaining walls</b>											
<b>2017-18</b>											
var	var	various locations	as required following road inspections				20	20.0		Tayside Contracts	
3	U105	Upper Allan Street	carry over 2016-17				30	50.0			
3	U/C	Back Brae Blairgowrie	Construct retaining wall and reinstate footway	15			20	70.0		Tayside Contracts	Footway fallen away
4	U/C	21 Chapel St Aberfeldy	Take down and reconstruct retaining wall	11.2			15	85.0			Retaining wall supporting road fallen away into garden contact house holder prior to design
<b>DRAINAGE</b>											
<b>2017-18</b>											
2	A94	Drumkilbo	Install new carrier pipe to address carriageway flooding				116	116.0		Tayside Contracts	Work required following flooding Dec 2015
4	A826	Moness Aberfeldy to 690 m South Wards	Install new drainage system in road	690		120.00	82.8	198.8		Tayside Contracts	existing pipe damaged throughout water runs into Aberfeldy
4	A827	Logierait	Replace soakaways to				10	208.8		Tayside Contracts	Following success of work 2014-15 further

			prevent /reduce flooding								along road
5	A923	Sawmill Brae, Dunkeld	Construct surface water drainage system in carriageway	200		230.00	45.0	253.8	DT	Tayside Contracts	Continuous flooding and freezing during winter months - phase 1 completed 2016-17 remaining work before overlay
2	C422	New Alyth Road	Install new drainage system in road	100		209.48	20.9	274.7		Tayside Contracts	Water ponding road flooded and freezing during winter months
var	var	various locations	minor drainage improvements as required by road supervisors				150.0	424.7	RMP	Tayside Contracts	small projects as required by supervisor throughout year
<b>2018-19</b>											
4	C447	West of Cluny road	Phase 3 Drainage				15.0	15.0	RMP		Continuous flooding and freezing during winter months
4	U117	Drummond Hill	Install new drainage system and kerbing prior to future overlay	323		155.93	50.4	65.4	RMP		no drainage in this section of road, causing surface deterioration
5	A984	Junction B947 to culvert at Mill hill house	Install positive drainage	280		233.00	65.2	130.6			Continuation of water running down brae and freezing
4	B8079	Killiecrankie	Install new drainage system	323		140.00	45.2	175.8			Continuous flooding and freezing during winter months
5	A984	Junction B947 to Meikle Fardle	Construct road surface water drainage system in verge	250		209.48	52.4	228.2			Continuous flooding and freezing during winter months
2	B954	West Jordanstone to Cotton of Balharry	Replace existing drainage with larger pipe	118		209.48	24.7	252.9			Drain requires replace as part on the ongoing flooding issues
2	C425	Lochbank	Install new carrier drain	380		140.00	53.2				Consider reducing size of pipe due to length of road require to be

											drained. Also consider speaking to land owner to install pipe in field to reduce cost and disruption to road users
4	U165	Edradour Distillery									
<b>Patching and reinstatements (recurring)</b>											
Various	Various	use of hot box for defects					100.0	100.0			Tayside Contracts
Various	Various	use of jetpatcher					80.0	180.0			Competition
	*	U94 Kynballoch	Pre surface dress	800 sq. m patching and 2 overlay patches			40.0	220.0			Tayside Contracts
	*	A926 from Roundabout to Angus boundary - 30 sq. m	Pre surface dress	30			5.0	225.0			Tayside Contracts
		A984 Main Street Spittalfield	Pre surface dress	300		30.00	10.0	235.0			Tayside Contracts
		A984 Main road Meikleour	Pre surface dress	300		30.00	10.0	245.0			Tayside Contracts
	**	A94 from Meigle to Coupar Angus	Pre surface dress	2000		45.00	90.0	335.0			Tayside Contracts
	*	U104 Haugh road Rattray from Old Mill Road to End 3 overlay patches and 500 sq m patching	Pre surface dress	3 overlay patches and 500 sq. m patching			40.0	375.0			Tayside Contracts
	*	B847 Calvine	Pre surface dress	500		20.00	10.0	385.0			Tayside Contracts



	*	C438 Milestone to Crossroads	Pre surface dress	500		20.00	10.0	395.0		Tayside Contracts	
	*	C437 Crossroads to A93 2000 sq. m	Pre surface dress	2000		20.00	40.0	435.0		Tayside Contracts	
		U164 Balchandy 500 sq. m	pre surface dress	500		30.00	15.0	450.0		Tayside Contracts	
		Minor patching by hotbox at other sites	Pre surface dress				20.0	470.0		Tayside Contracts	
	*	C19 Larghan Park	taycoat	500		40.00	20.0	490.0		Tayside Contracts	
	*	Wolfhill	taycoat	200		40.00	8.0	498.0		Tayside Contracts	
	*	C423 Boatman's Cottage to U103 aberbothrie	taycoat	500		40.00	20.0	518.0		Tayside Contracts	
	*	C424 from B954 to U102 Lieftie	taycoat	1000		30.00	30.0	548.0		Tayside Contracts	
	*	U160 Glen Lyon ( Bridge of Balgie West)	taycoat	1000		35.00	35.0	583.0		Tayside Contracts	
	*	B847 Balmore to Trinafour	taycoat	1000		35.00	35.0	618.0		Competition	
	*	Kinloch Rannoch Village	taycoat	400		35.00	14.0	632.0		Competition	
	*	C450 Schiehallion Road( Tomphubil west)	taycoat	800		35.00	28.0	660.0		Competition	
	*	A827 Kenmore to Fearnan	HRA	750		40.00	30.0	690.0		Tayside Contracts	
		C452 Foss Road ( Loch Tummel section)	taycoat	1000		35.00	35.0	725.0		Tayside Contracts	

	*	A984 Dunkeld to Dungathill	HRA	4000		25.00	100.0	825.0		Tayside Contracts	
	*	B9099 Luncarty to Stanley	HRA	2500		35.00	88.0	913.0		Competition	
	*	A93 from Bridge of Cally to B950	taycoat	3100		30.00	93.0	1006.0		Tayside Contracts	
		B954 hotbox 2 days	HRA					1006.0		Tayside Contracts	
		A94 Coupar Angus to Balbeggie hot box 5 days	HRA				10.0	1016.0		Tayside Contracts	
		Patching Carse of Gowrie not yet identified	HRA	1250			52.0	1068.0		Competition	

**Capital Footway Budget £154,000**

**FOOTWAY WORKS**

**2017-18**

	var	various streets	Minor footway repairs				10.0	10.0		Tayside Contracts	
4	A924	Perth road Pitlochry from Aldour Gardens to BP	Resurface footway				8.0	18.0		Tayside Contracts	
3	U/C	Albert Street Sidlaw Crescent Kinpurnie Drive Alyth		575	862.5	43	37.1	55.1		Tayside Contracts	Surface failure Hold Albert St until new School built
4	U/C	Duntaylor Avenue.	Resurface footway	134	242	35	8.5	63.6		Tayside Contracts	Surface previous Slurry seal now worn off trips and no provision for wheelchairs
4	Unc	Moness Terrace Dunkeld Street to Carpark	Reconstruct Footway	60	120	80.00	9.6	73.2		Tayside Contracts	Surface failure

3	U/C	Shaw St Blairgowrie	Resurface footway	310	465	35	16.3	89.4		Tayside Contracts	Surface in poor condition
3	U/C	Ferguson Park Rattray	Slabbed Housing footways No 2 to 53	300	1250	45	56.3	145.7		Tayside Contracts	Multiple broken and uneven and open jointed slabs
	Var	Slurry seal footways					50.0	195.7		Tayside Contracts	
<b>2018-19</b>											
2	C18	Junction A923 to Kettins									Road surface has been overlaid multiple times. Kerb line in very poor condition, kerb up stand vary between 50mm to 90mm, multiple kerbs require replace
3	U/C	Glenshee Drive Rattray	Reconstruct Footway	496	545	80	43.6				
3	U/C	Glenshee Drive Rattray	Slabbed Housing Footways	360	648	50	32.4	32.4			
3	U/C	Glenalmond Road Rattray	Slabbed Housing Footways	1080	313.2	50	15.7	48.1			
3	U/C	Glenisla Court /Glenshee Drive	Slabbed Housing Footways	386	694.8	50	34.7	82.8			
3	U/C	Glendevon Court Rattray	Slabbed Housing Footways	199	359	50	18.0	100.8			Restore footway surface remove tripping hazards
3	A93	Balmoral Road Rattray	Resurface footway	300	360	40.79	14.7	115.5			Surface linking two communities
5	B867	Bankfoot to Waterloo	Resurface dust footway with DBM	460	598	35	20.9	136.4			Surface in poor condition
3	Unc	Blackloch Crescent Carsie	Resurface footway	187	300	35	10.5	146.9			Surface in poor condition wheelchair access require
3	U/C	Upper Craighall Place Rattray	Resurface footway	450	540	42.72	23.1	170.0			Road surface has been overlaid multiple times. Kerb line in very poor

											condition, kerb up stand vary between 50mm to 90mm, multiple kerbs require replace
<b>2019-20</b>											
5	A827	Ballinluig Flyover	Resurface footway	126	115	42.72	4.9	4.9			Surface pushed up requires investigation
5	unc	Nicol Drive Bankfoot	Reduce width of footway	125	225	100	22.5	27.4			Surface in poor condition continuous over run over
4	B847	Main road Calvine	Resurface footway	164	246	8	1.968	29.4			Surface in poor condition
4	B847	Calvine Old School to Old Shop	Resurface footway	146	246	42.72	10.5	39.9			Surface failure
5	A923	Dunkeld Bridge	Resurface footway and carry out minor kerbing	250	250	42.74	10.7	50.6			Surface failure
3	Unc	Keay St Blairgowrie	Resurface footway	210	315	40.79	12.8	63.4			Restore footway surface remove tripping hazards
3	Unc	Riverside Road Rattray	Resurface footway	95	95	40.79	3.9	67.3			Restore footway surface remove tripping hazards
4	Unc	Taybridge Drive	Resurface Footway	320	640	42.74	27.4	94.6			Restore footway surface remove tripping hazards
4	A827	Dunkeld St Aberfeldy from Co-op to Faragon Drive	Reconstruct Footway	22	66	73.92	4.9	99.5			Restore footway surface remove tripping hazards
3	Unc	Jessie Street Blairgowrie	Resurface footway	120	118	40.79	4.8	104.3			Restore footway surface remove tripping hazards
4	Unc	Taybridge terrace Aberfeldy	Resurface footway	290	522	42.74	22.3	126.6			Previous slurry seal spalling off
2	A923	Coupar Angus to Kettins	Resurface dust footway	1440	1728	42.72	73.8	200.5			Replace dust footway

2020-21											
2	A94	Coupar Angus to Woodside	Reconstruct footway	2160	3240	45	145.8	145.8			Replace dust footway
4	A924	West of Gate House	Extend kerb line	75		35	2.6	148.4			Prevent water discharging onto road surface
3	U/C	Upper Mill St Blairgowrie Junction A93 to End	Resurface footway		97	42.72	4.1	152.6			Surface in poor condition
4	A823	Athole Road Pitlochry Dysart Brae to Clunie Bridge Road	Slurry seal footway	280	420	7	2.9	155.5			Surface patched by utilities require sealed
4	A827	Bank St Aberfeldy	Resurface	78	144.6	35	5.1	160.6			Surface in poor condition
2	Unc	Cambridge Quad Alyth	Resurface footway	136	245	42.74	10.5	171.0			Surface failure